

C.V. Joint Banding Tool with Cutter

Tool is easily removed, by sliding sideways after winding has been completed.

Instructions :

Place band around boot and through nose of tool and through slot in winding body. Using a 1/2" socket wrench or by hand wind the band until sufficient tension is applied. Rotate handle over the boot to lock the band. Slide tool Free-end down with a hammer.

1. Wrap free-end clamps 3/8" or 1/4" roll band and clip around boot. Thread the band through the clip, into the nose of the tool and through the winding mandrel slot.
2. Place a 1/2" ratchet wrench on the winding mandrel and turn. When sufficient tension has been applied, rotate the tool over the boot, bending the band back onto the clip.
3. It applies tension and has a built-in cutter.
4. To complete clamping, fold down the remaining tail of the band into the clip and secure it by tapping down the ears of the clip.

NOTE : For added strength, double-wrapped band is recommended.

**CAUTION : Wear Safety Goggles.
Patent Pending.**

Lifetime Warranty

KD Tools

Manufactured in Taiwan to Danaher Specifications
Fabricado en Taiwán a las especificaciones de Danaher

